
Contents

Fixing the Weighing Pan	 1
Protection Device Disassembly Steps	 1
Precautions	 1
Descriptions of Keys	 2
Functional Operation of Keys	 2
Panel Illustration	 3
Single Point Calibration of Weight	 3
Linearity Calibration of Weight	 4
Parameter Setting	 5
Parameter Functional Description	 6
Units Conversion Table	 7
Cross-reference Table of Full Loads	 7
RS-232 Serial Interface	 8

Weighing Pan Fixing Steps



- 1. When installing the weighing pan, tighten the fixing screw in the centre of the plastic weighing pan.
- 2. Unscrew and remove the shipping protection screw on the side of the scale.
- 3. After removing the shipping protection screw on the side of the scale, fasten the shipping protection buckle.

Protection Device Disassembly Steps

- 1. In the upright position, locate the shipping protection screw device on the left side of the scale.
- 2. Before using the scale, unscrew counterclockwise and remove the shipping protection screw.
- 3. Before transporting the scale, hold the shipping protection screw down inwards and tighten it clockwise.

Precautions

- 1. Please pay attention to the environment when performing weight calibration on the scale. Avoid wind blow and vibration.
- 2. Use of wrong batteries or wrong wiring may cause danger.
- 3. 10 minutes warm up till the RED light off before activating the scale.

Descriptions of Keys

ON/OFF: The on/off key for switching on/off the equipment.

ZERO: The zero key for resetting the equipment, functional only when weight is within 4% of the weighing

capacity.

TARE: The tare key for deducting the weight of container on the weighing pan.

MODE: The switching key to select weighing, counting and percentage modes in turn.

UNIT: Weighing units switching key. (13 kinds of units)

SMPL: In the weighing mode, the key is for switching on/off backlight; in the counting and percentage

modes, the key is for sampling, by pressing which, you may select sample size of 20, 50, 100, 200

or 500 in turn.

Functional Operation of Keys

Weighing:

Press $\lceil \text{ON/OFF} \rfloor$ key, the screen will have full display and start counting down. When the screen displays $\boxed{0.00 \text{ X}}$, you can start weighing. If you need backlight, press $\lceil \text{SMPL} \rfloor$ key.

Counting:


Press [MODE] key, the screen will show XXXX pcs, then press [SMLP] key, and the screen will show S= 20pcs. You may select sample size of 20, 50, 100, 200 or 500 in turn by pressing [SMLP] in succession. After selection, put the sample on the weighing pan and start counting operation when you hear a beep sound. (Automatic averaging function is provided for simple counting)

Percentage:

Press $\lceil \textbf{MODE} \rfloor$ key, the screen will show $\lfloor \textbf{XXXX} / \textbf{S} \rfloor$, then press $\lceil \textbf{SMLP} \rfloor$ key, and the screen will show $\boxed{\textbf{S}=20 \ \%}$. You may select sample size of 20, 50, 100, 200 or 500 in turn by pressing $\lceil \textbf{SMLP} \rfloor$ in succession. After selection, put the sample on the weighing pan and start using the percentage function when you hear a beep sound.

Notes:

- 1. Min. unit weight of sample >=1 readability (e.g.: unit weight of sample of 300g is at least bigger than 0.01g)
- 2. When weight is unstable, the **STABLE** indicator will go off.
- 3. After warming up the machine, the **WARMING** indicator will go off.



1	Level	6	Stable indicator
2	Warming up indicator	7	Tare key
3	Sampling/Backlight key	8	Zero key
4	Function selection key	9	Weight display window
5	Unit conversion key		

Single Point Calibration of Weight

Step 1: Power off while holding down 「MODE」 key, and then press 「ON/OFF」 to switch on the scale. The screen will show the following:

Count

Step 2: Press the **MODE** key, the screen will show the following:

CAL

Step 3: Press the **\[UNIT \]** key to start zero point calibration. Make sure there is nothing on the weighing pan. The screen will sho<u>w the following:</u>

ZEro

Please wait for the screen to show:

_		_	
	^ .		
	_		
•	_		

The calibration can be done at the point of 1/3 load, 2/3 load or full load. Choose the one you need and place the corresponding weight onto the pan.

If place 1/3 of load onto the pan, the

screen will show:

on1

If place 2/3 of load onto the pan, the

screen will show:

on2

If place full load onto the pan, the

screen will show:

on3

Step 4: Place weights of equivalent weight onto the pan, wait for a beep sound and the screen will show:

PASS

Step 5: Press [MODE] and then press [SMPL], the screen will show:

busy

Step 6: After countdown, the single point calibration is completed and the scale returns to the normal weighing mode.

Linearity Calibration of Weight

Step 1: Power off while holding down **[ZERO]** and **[TARE]** keys, and then press **[ON/OFF]** to switch on the scale. The screen will show the following:

L-CAL

Step 2: Clear the weighing pan, then press **TARE** and the screen will show the following: (zero point calibration)

on0

Step 3: Wait for a beep sound and the screen will show the following:

on1

Step 4: Place 1/3 of load on the weighing pan in ten seconds ,Waiting for a beep sound and the screen will show the following:

on2

Step 5: Place 2/3 of load on the weighing pan in ten seconds ,Waiting for a beep sound and the screen will show the following:

on3

Step 6: Place full load on the weighing pan in ten seconds, Waiting for a beep sound and the screen will show the following:


PASS

Step 7: Clear the weighing pan, then press **TARE** and the screen will show the following:

busy

Step 8: After countdown, the linearity calibration is completed and the scale returns to the normal weighing mode.

Parameter Setting



	↓	1		
	Pr Fu	External device	PC/ SH-24	Item 10, Page 7
	\	1		
	diV-Z	Display range	Zero0/1/2/3/4/5	Item 11, Page 7
1.			ount, press the「 UNIT 」key, th 」to return to LCD display <u>Co</u>	
2.	the screen displayed, "d between ON unit displaye	Nand OFF [to use the discussion of the last the	unit , press UNIT to enter i or oFF g, "on" means to se the current unit displayed. Properties of the unit displayed select "on", if the ess UNIT to select from 13 press MODE to return to LC	to use the current unit ress 「SMPL」 to switch you do not require the kinds of weighing units,
3.	mode. LCD		InitU , press 「UNIT」 to e c means the initial unit is selected ess「MODE」 to return to LCD of	
4.	selection. Loselect the au	uto power-off time, the neans No auto poventing the neans No auto poventinutes, 60-means	Auto , press 「UNIT」 to end X means Auto Power-off selection press「MODE」 to return to wer-off, 5- means 5 minutes, so 60 minutes (in case of instance)	ction. Press「 UNIT 」 to LCD display Auto . 15- means 15 minutes,
5.	Rate select	CD display shows [ion. LCD display [select the desired RSAud]. [2400, 480]	XXX X represents the RSS-232 baud rate, then press M	enter the RS-232 Baud S-232 baud rate. Press ODE to return to LCD
6.	selection. Lo	CD display d X	ZEro, press 「UNIT」 to X represents the auto zero range, then press 「MODE」 to	ange. Press 「UNIT」to

Electronic Scale 6

FiL

filter level and press MODE to return to LCD display

higher the value is, the higher the filter level is)

7. When the LCD display shows

8.

 \circ <u>\(\big| d0, 1, 2, 3, 4, 5_{\(\)} \)</u> (the higher the value is, the wider auto zero range is)


LCD display FiL X X means the filter level. Press 「UNIT」 to select the desired

When the LCD display shows LigH , press UNIT to enter backlight setting mode.

, press **UNIT** to enter filter setting mode.

FiL

『FiL1, 2, 4, 8』 (the



12. Before entering function setting, press 「SMPL」 to end function setting and return to normal weighing mode. Press the 「MODE」 key continuously to select function setting modes.

diV-Z | Tzero0, 1, 2, 3, 4, 5 (means weight displayed when the weight exceeds the

Units Conversion Table

1 ct	[MET.CARAT]	=0.1999694	g
1 lb	[AVORIRDUPOIS POUND]	=453.59237	g
1 oz	[AVORIRDUPOIS OUNCE]	=28.349523125	5 g
1 dr	[AVOIRDUPOIS DRAM]	=1.7718451	g
1 GN	[GRAIN](U.K)	=0.06479891	g
1 ozt	[TROY OUNCE]	=31.1034768	g
1 dwt	[PENNY WEIGHT]	=1.55517384	g
1 MM	[MOMME] (JPN)	=3.749996	g
1 tl.j	[HONG KONG JEWELRY TAEL]	=37.4290018	g
1 tl.T	[TAEL](TWN)	=37.49995	g
1 tl.H	[HONG KONG TAEL]	=37.799375	g
1 t	[TOLA] (INDIA)	=11.6638038	g
1 oz/yd ²		=0.33898306	g
1 g/m²		=0.01	g

capacity)

Cross-reference Table of Full Loads

CAP	150	300	600	1500	3000
Gram	150X0.005	300×0.01	600×0.02	1500×0.05	3000×0.1
Carat	750.34X0.02	1500.70X0.05	3001.36X0.1	7503.4X0.2	15007.0X0.5
Pound(Avoir)	0.33080X0.00002	0.66160X0.00005	1.323X0.0001	3.3080X0.0002	6.6160X0.0005
Ounce(Avoir)	5.2926X0.0002	10.5855X0.0005	21.171X0.001	52.926X0.002	105.855X0.005
Dram(Avoir)	84.685X0.005	169.37X0.01	338.72X0.02	846.85X0.05	1693.7X0.1
Grain	2315.5X0.1	4631.0X0.2	9262.0X0.5	23155X1	46310X2
Ounce(Troy)	4.8240X0.0002	9.6480X0.0005	19.296X0.001	48.240X0.002	96.480X0.005
Penny weight	96.480X0.005	192.96X0.01	385.92X0.02	964.80X0.05	1929.6X0.1
Momme	40.012X0.002	80.025X0.005	160.05X0.01	400.12X0.02	800.25X0.05
Tael (HK Jewelry)	4.0088X0.0002	8.0175X0.0005	16.035X0.001	40.088X0.002	80.175X0.005
Tael (Taiwan)	4.0012X0.0002	8.0025X0.0005	16.005X0.001	40.012X0.002	80.025X0.005
Tael (Hong Kong)	3.9696X0.0002	7.9390X0.0005	15.878X0.001	39.696X0.002	79.390X0.005
Tola (India)	12.865X0.0005	25.728X0.001	51.456X0.002	128.640X0.005	257.28X0.01
oz/yd²	442.49X0.01	884.99X0.01	1770.27 X0.01		
g/m²	15000.5 X0.5	30000 X1	60000 X1		

Note: Full Load = Capacity + (Readabilityx9)

RS-232 Serial Interface

The 9PIN connector at the right back is a RS-232 standard interface. Pin 3 is for output, Pin 5 is for grounding and the rest have no functions.


BAUD RATE: 2400 OR 4800 OR 9600 bps

DATA BIT: 8


PARITY BIT: N (NONE)

STOP BIT: 1 CODE: ASCII

BIT FORMAT:



DATA FORMAT:



ST: STABLE UT: UNSTABLE

GW: GROSS WEIGHT

SP: SPACE

Examples: ST GW + 150.00 g

UT NW - 80.00 ct

PC Program: 10 OPEN "COM1:9600,N,8,1,RS,DS,LF" AS #1

(BASICA) 20 INPUT #1,A\$

30 PRINT A\$

40 GOTO 20

50 END